



# OPERATING INSTRUCTION MANUAL

## BFN-TR1800 (Megohmmeter)

### PRODUCT INTRODUCTION

The BFN-TR1800 Megohmmeter is a dependable and easy to use audit kit for conductive and dissipative surfaces. This meter is designed to be used in all facets of production materials including engineering, maintenance, quality control, incoming inspection, manufacturing, research, or sales departments for testing anti-static mats, floor finishes, paints, wrist straps, smocks, footwear, bags, and containers.

The BFN-TR1800 measures surface resistivity, surface resistance, temperature, and humidity. It is designed to test material surfaces for electrical resistance or resistivity according to EOS/ESD, CECC, ANSI, ASTM, and UL test procedures and standards.

The built-in internal parallel electrodes comply with DIN EN 100 015/1 and ANSI/ESDA-S11.11 standards. The two 5 pounds electrodes can be externally connected for test according to IEC61340-4-1, ANSI/ESDA S4.1 and ANSI/ESDA S7.1.

When using the built-in parallel electrodes, the meter's test values for surface resistivity are in ohms per square (ohms/sq). And when using the external 5-pounds electrodes, the meter's test values for resistance are in ohms.

### TEST LIMITS

- Resistivity:  $10^3 - 10^{12}$  ohms/sq
- Resistance:  $10^3 - 10^{12}$  ohms
- Measuring Voltage: 10V and 100V
- Relative Humidity: 10% - 90% RH
- Temperature:  $0^\circ - 37.7^\circ\text{C}$

### PRODUCT PHOTO



### PACKING LIST

- TR1800 Meter
- Two 5lbs probes
- One metal plate (Size: 142mm x 67mm)
- One alligator clip and one ground cord
- Two accordion cables
- 9V battery
- Foam lines carrying case
- Certificate of Calibration

## **PRODUCT SPECIFICATIONS**

- Size: L190mm x W100mm x H40mm
- Weight: 293g (approx.)
- Power: Battery operated PP3 9V
- Test Range:  $10^3 - 10^{12}$

## **DECADE SCALE**

- $10^3 = 1$  kilo ohms
- $10^4 = 10$  kilo ohms
- $10^5 = 100$  kilo ohms
- $10^6 = 1$  Mega ohms
- $10^7 = 10$  Mega ohms
- $10^8 = 100$  Mega ohms
- $10^9 = 1$  Giga ohms
- $10^{10} = 10$  Giga ohms
- $10^{11} = 100$  Giga ohms
- $10^{12} = 1$  Tera ohms

The test value is indicated on the LCD display. Unlike meters with LED indicators, the TR1800 will show the actual resistance value. 27Mohms ( $2.7 \times 10^7$ ) is displayed as 2.7 e07 ohms/sq.

## **TEST VOLTAGE**

- The test voltage ranges are 10V and 100V. According to ESDA standards S4.1, S7.1, and S11.11, 10V should be applied for the conductive surfaces less than  $10^6$  and 100V for materials greater than  $10^6$ .
- The meter cannot apply the correct voltage automatically, it will advise you to change to the proper setting manually.
- As defined by the ESD association, values indicate the following:

Voltage	Range	Definition
10 volts	$< 10^6$ ohms per square	Conductive
100 volts	$10^6 - 10^{11}$ ohms per square	Dissipative
100 volts	$> 10^{11}$ ohms per square	Insulative

## **A NOTE ABOUT VOLTAGE**

In previous years, people desiring to measure resistivity or resistance that follows the ASTM D264, ASTM 991, NFPA 56A, or NFPA 99 test standards. These procedures required people to test at either 500 or 1000 volts. This caused concern regarding safety of the person doing the tests. The ESDA standardized the test procedures so that lower volts could be used at specific ranges.

The TR1800 meter uses a 9V battery. Some meters with 9V battery do not give the accuracy that you need to perform the tests especially at values higher than  $10^7$ . The TR1800 is built with a transformer that converts the 9V charge from the battery to 10V or 100V (which ever value is selected). The meter applies constant charge over the complete voltage range. Accuracy depends on the applied voltage, temperature, and humidity.

## **TEMPERATURE AND HUMIDITY**

The humidity and temperature affect the electrical properties of the material being tested. The combination of low humidity and low temperature will give the highest electrical resistance results or slowest dissipation time. At high humidity, a thin layer of water is condensed or absorbed on or in the material being tested. This is true of hygroscopic additives that are added to a material to increase the electrical conductivity. These additives will allow moisture to be absorbed in the materials they are added to.

At elevated temperature, the mobility of free electrons is increased thereby increasing the materials conductivity. This especially true for carbon black, metallic oxides, metals, and other materials added to a material. When the material is at a lower temperature, built in stresses occur which might increase the resistance due to increased distance between the conductive additives. Thus, humidity and temperature must be known.

## **RECORDING DATA**

ANSI/ESD Association and European CECC recognized the environmental effects of the test measurements and specify in their standards that they measured and recorded. It is possible to test or manufacture a material at high humidity and pass all the test specifications, but when customer receives the material and uses it at a lower humidity or temperature the materials fail to pass the specifications. This can cause rejects and loss of products. Both ESD S4.1 (ESD Protective Work Surface) section 6.2.4 and ESD S7.1 1994 (Resistive Characterization of Materials Floor Materials) section 5.2.4 and 5.3.3 require reporting of temperature and humidity at the same time of testing. ANSI/EOS/ESD S11.11 1993 (Surface Resistance Measurement of Static Dissipative Planar Materials) Section 11.0B states, “report the condition period, relative humidity, and temperature.”

## **MEASURING WITH INTERNAL ELECTRODES**

The parallel resistivity probe method complies with EOS/ESD S11.11. It is used to give fast electrical resistivity measurement on flat homogeneous materials. It may be used on multi-layered materials, but this should be noted along with the temperature and humidity value on the data sheet report.


When the measurement is taken between the tester’s two mesh rails, the tester will indicate the surface resistivity of the material being tested.

- Prior to testing, make certain that the surfaces to be tested are clean and free of contaminants.
- Allow the meter to equilibrate to the atmospheric condition of the testing area. It may take half hour for the meter to adjust to the new environment condition.
- Place the meter on the desired surface to be tested.
- Move switch to the desired test voltage (10V or 100V), depending on the target range of the material.
- Press and hold the red button with approximately 5lbs of applied force. The meter will display the humidity and temperature of the testing area. And after approximately 10 seconds, the meter will display the surface resistivity in ohms per square.
- The meter will keep updating while the button is held down. The last reading will display approximately 20 seconds after the button is released.

## **MEASURING WITH EXTERNAL ELECTRODES**

When the measurement is taken using the 5lbs external probes, the tester will indicate the resistance of the material in ohms, though the displays says ohms/sq. By utilizing these probes to the TR1800’s socket, it is possible to measure Point-toPoint (RTT) resistance, Surface-to-Ground (RTG), and volume resistance. Using these probes will allow compliancy with various standards including ANSI/ESDA S4.1 for Work Surface – Resistance Measurements, ANSI/ESDA S7.1 Resistive Characterization of Materials – Floor Materials.

When auditing is finished, unplug the cables and store probes in the protective case. If jacks are damaged or left in the open position, the internal probe will not engage when testing for surface resistivity.



## **RESISTANCE BETWEEN TWO POINTS (RTT)**

RTT measurements can be used for the evaluation of floors, chairs, carts, work surfaces, and other ESD controlled materials and products. Procedures vary regarding sample preparation, probe preparation, and spacing of 5lbs probes. Select and read the correct test procedure or standard for the desired measurement.


- Connect one end of each of the banana test leads into the sockets of the meter and connect the other end of the test coil cords into the 5lbs probes.
- Place both probes on the material according to test procedures or standard being used.
- Press “TEST” button and the value will be displayed on the LCD screen.
- When performing test, do not touch lead wires or probes. Avoid overlapping of wires to ensure accurate readings.



### **MEASURING RTT ON DISSIPATIVE FLOORING**

Taking routine measurements of tiles with dissipative finish will ensure proper maintenance routines and will indicate any problems that may arise. Good record keeping will insure success when developing and maintaining a maintenance program.

To get an average measurement of a floor, map out a 4' x 4' section and conduct 5 tests (one at a time) within the square. Conduct a test for each side of the square and a final test diagonally through the center as shown in the drawing. Each RTT test utilizes the 5lbs probes placed 3 feet apart (36 inches). Connect the test leads to the meter and attach the 5lbs probe to the end of each lead. Press and hold “TEST” button until a value is displayed.



### **RESISTANCE TO GROUND (RTG)**

RTg measurements can be used for the evaluation of floors, chairs, carts, work surfaces, and other ESD controlled materials and products. Keeping record of test results will provide a reference.

### **MEASURING RTG ON DISSIPATIVE FLOORING**


For testing resistance on floors, ESDA S7.1 requires a minimum of 5 RTG per 5000 SqFt.

- Connect the leads for the external electrodes to the meter.
- Attached one lead to a 5lbs probe and place the probe on the floor that is being tested.
- Attach the other lead to an alligator clip and connect to a ground able point (RTGP). If using a ground adapter plug, plug the banana lead into the adapter after the adapter is plugged into the receptacle.



## **MEASURING RTG ON DISSIPATIVE TABLE MATS**


- To test RTG for a work station, used the first cable to connect the meter and a 5lbs probe and put the probe on the work surface. Then used the second cable to connect the meter to a groundable point (RTGP).
- To attach cable to RTGP, slip the alligator clip to the banana jack and connect it to the ground snap or connect the banana jack to a common point ground plug.
- Press “TEST” button and the value will be displayed on the LCD. When performing test, do not touch lead wires or probe. Avoid overlapping of lead wires to ensure accurate readings.
- Resistance values are in ohms. When recording test values also record the temperature and humidity as environment test reference.



## **VOLUME RESISTANCE MEASUREMENT**

Volume resistance measures the electrical path through the material.

- Use cables to connect the meter and the two 5lbs probes.
- Place sample material on a conductive metal plate (such as stainless steel). Place one of the 5lbs probe on the material so that the material is sandwiched between the probe and the metal plate.
- Place the second 5lbs probe on the conductive metal plate.
- Press “TEST” button and value will be displayed on the LCD. Volume resistance is in ohms/cm.



## **CALIBRATION**

Calibration is recommended annually. The TR1800 meter comes with a calibration certificate when ordered. After 1 year, the meter can be sent back to HORB FACTORY for a new calibration certificate (Lab Fee is applied) or it can be sent to a certified calibration lab. The meter also comes with a CE mark approval. A tester resistance can be applied across the parallel bars to verify if the meter is within specification using a resistance decade box. Calibration can be obtained by contacting HORB office or by a certified calibration laboratory.

## **CALIBRATION INSTRUCTION**

The BFN-TR1800 meter is calibrated to be most accurate in the most widely used range ( $10^6 - 10^8$ ). The laboratory calibrates meters between 30%-40%RH at 65°F – 75°F. If you are using the meter in atmospheres different that mentioned, it is strongly advised to recalibrate the meter to your conditions.

- Purchase 1%  $10^3 - 10^{12}$  ohm resistors, high accuracy relative humidity hygrometer, and high accuracy thermometer.
- Open the meter, be careful not to disturb or break the two wires connecting the power button from the circuit board.
- Observe on the right lower side of the meter printed circuit board four (4) calibration pots.
- Allow the meter to equilibrate and normalize in the environment for 2 hours before testing.
- Using the supplied coil cords, attach alligator clips to the banana plug ends of the cords.
- Insert the 3.5mm ends into the meter jacks.
- Attached the ends of the resistors to the ends of the alligator clips.

- The top pot is for humidity. The next pot under the top is for resistivity. The third pot is for temperature. The last pot on the bottom is to fine tune resistivity. Adjustment is done with a small screw driver. Clockwise is to increase the value, and counter clockwise to decrease the value.
  - Press the power button and compare the resistor value, humidity, and temperature to the parameter to be calibrated.
  - Release the power button and slowly turn the correct adjustment pot.
  - Re-press the power button, and observed the LCD screen. Re-press and adjust the pot if necessary.
  - Close case and tighten the 4 screws.
  - Press the power button to verify the meter is working.
  - Test at 10V for values under  $1 \times 10^6$  ohms. Test at 100V for values over  $1 \times 10^6$  ohms.
  - Tolerance from  $10^3 - 10^8$  ohms is 10%,  $10^9 - 10^{10}$  ohms is 15%, and  $10^{11} - 10^{12}$  ohms is 25%.
  - When testing at high resistance values, ground the meter with a ground cord in the grounding jack. Electrical interference and ESD can affect the tolerances and accuracy.
  - The tolerance for temperature and humidity are;
    - $\pm 30^\circ$  Fahrenheit up to  $700^\circ\text{F}$
    - $\pm 3\%\text{RH}$  up to  $70\%\text{RH}$
    - $\pm 50^\circ\text{F}$  over  $700^\circ\text{F}$
    - $\pm 5\%\text{RH}$  over  $70\%\text{RH}$
  - To increase the accuracy, adjust the calibration at the temperature and humidity meter will be used. For example, if you were using the meter at  $700^\circ\text{F}$  and  $70\%\text{RH}$  then you would calibrate the meter exactly at those conditions using a 1% accuracy standard thermometer and humidity meter.
- \*Should calibration traceable to the NIST be required, please call HORB factory, and directly arrange for calibration.**

Operating manual is only for BFN-TR1800 users. It includes the tester's components, operation and some concerning information, some upgrading property with continuing stability, slightly difference will be allowed with operation and manual.



#### Suppliers Information



2018 Shenzhen HORB Technology Corp. Ltd. / Printed in China